

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer Muhammed Mahud
2. Name of the School Mother Theresa Memorial Central School, Palleppara.
3. Location with name of Education District/ Sub. District Palleppara, Pongode (P.O)
4. Classification of Building as specified in column 4 of the application for fitness certificate and size. Block - I 28.40 x 8.60 R.C.C. Two stored building
G.F. & F.F - 2 x 4 (8 Rooms)
Block - II 28.10 x 10.60 - R.C.C. Two stored building
Block - III 24.30 x 8.20 R.C.C. Two stored ^{G.F. & F.F.}
6.48 x 6.81 R.C.C. Two stored Office II - 10 x 8.55
G.F. R.C.C.
5. Period for which the certificate is issued 2025-26
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner Nil
8. Whether maintenance works have been done properly Nil
9. Whether the structure is sound or not for conducting classes Yes


The structure is sound under normal weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 26.06.25 and found to be fit / unfit to conduct classes, for the period 2025-26 Academic Year for the reasons stated above.

Place: Pongode
Date: 28.06.25



(Seal)

Mahud
Assistant Engineer

Assistant Engineer
L S G D Section
Pongode